



25X1A

Approved For Release 2002/10/09 : CIA-RDP66B00664R000400100064-6

[REDACTED] (IN 67789)

S E C R E T

PAGE TWO

ELECTRICITY MARKS INTERMITTENTLY THROUGHOUT FRAMES 1 A 563 ON 9L AND 9R. MOST S. E. MARKS ORIGINATED FROM DATA CHAMBER EDGE. ON 9L STRIP ONE LASH TWO INCHES WIDE, THREE INCHES FROM DATA CHAMBER EDGE. ORIGINAL BREAKDOWN ACCOUNTED FOR MUCH EDGE STATIC. CAUSE HAS BEEN ELIMINATED. STILL UNKNOWN IS ONE SLASH TWO INCH STRIP ENCOUNTERED IN PREVIOUS TAKES. SCATTERED MINOR PINHOLES AND ABRASIONS ENCOUNTERED THROUGHOUT FIRST HALF OF TAKE. PINHOLES IN FRAMES 680-1180 (9L) CAUSED BY PROCESSOR ROLLER. CORRECTED DURING PROCESSING. MANUFACTURING SPLICES IN FRAMES 359 AND 2746 (9L) AND 1726 (9L) AND 2736 (9L).

END OF MESSAGE